



**TESTING SERVICE CORPORATION**

*Corporate Office:*

360 S. Main Place, Carol Stream, IL 60188-2404  
630.462.2600 • Fax 630.653.2988

*Local Office:*

457 E. Gundersen Drive, Carol Stream, IL 60188-2492  
630.653.3920 • Fax 630.653.2726

Local Office  
Carol Stream, Illinois

July 23, 2008

Mr. Jeremy Grey  
CenterPoint Properties  
1808 Swift Road  
Oak Brook, Illinois 60523

Re: L-70,614  
Section 29  
CIC North  
Joliet, Illinois

Dear Mr. Grey:

This letter has been written in connection with Section 29 located on the CIC North site in Joliet, Illinois. It is understood that local residents have indicated that unusual geologic features may be associated with this land. The subject property lies north of Laraway Road, between Patterson Road to the west and Brandon Road to the east, extending up to the Commonwealth Edison right-of-way on the north.

We are not aware of any unusual geologic features present in Section 29. Following are comments that can be made in connection with this statement:

- We have looked and not been able to find any Illinois State Geologic Survey publications which make specific mention of geologic features in Section 29.
- The eastern end of the Sandwich Fault runs through the Joliet area. However, it lies approximately 4 miles southwest of Section 29 in the site vicinity.
- We are not aware of Karst topography or sinkholes being present in the Joliet area or on Section 29.
- TSC has drilled at least 30 soil borings in Section 29, extending up to 200 feet below existing grade. Soil conditions primarily consist of lake plain deposits and cohesive glacial till. Bedrock consists of Silurian Dolomite. These are considered typical of the area as well as being consistent with geologic mapping.
- A site reconnaissance was performed in connection with this letter. No unusual land forms were observed. The majority of the site is farmed except for a rock quarry located off Brandon Road, various wooded areas in the north-central area, and a low-lying area lying west of Patterson Road (recently wooded).

Please call if there are any questions or if we can be of further service.

Respectfully submitted,

TESTING SERVICE CORPORATION

  
Michael V. Machalinski, P.E.  
Vice President

MVM:cn

*Providing a Full Range of Geotechnical Engineering, Environmental Services, and Construction Materials Engineering & Testing*

Carol Stream, IL • Bloomington, IL • Cary, IL • DeKalb, IL • Gurnee, IL • Rockford, IL • Shorewood, IL • Tinley Park, IL